



Loop: General Work Sheet

Gen2 Pharmaceuticals
Ireland

Page 1 of 1

Date Printed: 15/10/14 14:44:19

Tag: <u>TT-LP001-001</u>	Work Order: <u>P/14/42/0011</u>	
Description: <u>Temperature on Reactor 001</u>	Safety: <u>N/A</u>	
Service: <u>N/A</u>	SOP: <u>General PPE</u>	
Company: <u>CompuCal</u>	Department: <u>Calibration</u>	
Plant: <u>Bleacher</u>	Location: <u>BOV</u>	Class: <u>Critical</u>
Tolerance: <u>N/A</u>	Interval: <u>1 Days</u>	Next Due Date: <u>10/2014</u>
Tolerance%: <u>N/A</u>	Tol Unit In: <u>N/A</u>	Range: <u>N/A</u>

Labels Updated: Yes: No: Failed By User: No: Yes:

Tasks: General Condition, Clean Probe

Setup Comments:

N/A

Entry Comments:

Tasks completed successfully.

Acceptance Comments:

Tasks completed without any issues, WO verified.

Conducted By: Felix Stubner

Date: 15/10/14

Accepted By: Eren Jaeger

Date: 15/10/14